



5050 First Avenue South Suite 102 Seattle, WA 98134 P.O. Box 1730 Seattle, WA 98111 Telephone: (206) 764-3000

3/16/07 CSK response

Fax Numbers: Executive (206) 764-3012 Sales (206) 764-3014 Credit (206) 764-3012 Warehouse (206) 762-3077 Cement Terminal (206) 764-7176

March 20, 2007

Elizabeth M. Gilpin, Inspector Puget Sound Clean Air Agency 1904 3rd Avenue, Ste. 105 Seattle, WA 98101

RE: Glacier Northwest, Inc. - Seattle Concrete Plant (Registration No. 11872)

Written Follow-Up on Compliance Status Report dated 3/16/2007

Dear Ms. Gilpin:

As requested from PSCAA, I am submitting this letter as a written follow-up to your Compliance Status Report dated March 16, 2007 for Glacier's Seattle Cement Terminal PSCAA registration # 11872. This plant is located at 5900 West Marginal Way SW in Seattle.

During your inspection you noted that baghouse #5 authorized under NOC 9379 was operating at 1" of water which was below the established range of 3 to 7". The operating pressure range of the #5 baghouse has been modified to 1" to 7" and the air O&M plan and inspection log updated. Additionally as noted in your inspection report, the operating staff at the cement terminal will now use a notation of "NR" on inspection logs when equipment is not running.

As you know, maintaining compliance with applicable clean air regulations is one of Glacier's top priorities. Please contact me at (206) 768-7612 or mhinck@glaciernw.com if you have any questions about this matter or require any additional information.

Sincerely

Viatt Hiller

Environmental Manger, Washington Division

cc:

Mark Wagy Scott Isaacson Steve Penswick

